ABSTRACT

A method for measuring overlay in semiconductor wafers includes obtaining diffraction based and imaging based measurements of the same target. The two separate measurements are then combined in a way that is consistent to both measurements to obtain an overlay measurement that has high precision and large range.

5